

POLE SETTING FOAM

Back Fill System

MIXING INSTRUCTIONS

MATERIAL REQUIREMENT: Prior to mixing, refer to Volume Index Chart in the Technical Data Sheet or use the calculator via the QR code below to determine the cubic feet of foam required to fill the void around the pole.

MIXING INSTRUCTIONS: Open the bucket and remove all contents of the bucket and set aside. Pour the contents of Part A bag and Part B bag into the supplied bucket. Use the supplied mixer to thoroughly mix the product taking care to mix the product at the corners and bottom. Mix product until the product abruptly changes color. Immediately pour into hole before expansion starts.

CAUTION: Material becomes very hot after mixing!

DISPOSAL: Disposal should be in accordance with Local, State, and Federal regulations. For unused or expired material, completely mix the 2 components together and dispose as non-hazardous waste after product has cured.


STORAGE & HANDLING: Store in an enclosed dry area out of the weather. Extreme temperatures should be avoided. The material must be stored between 50°F and 90°F.

Moisture Sensitive Product. Do Not Expose to Air.

KEEP OUT OF REACH OF CHILDREN.
Refer to Safety Data Sheet.
For trained personnel only.



© RAINBOW TECHNOLOGY CORP.
261 Cahaba Valley Parkway
Pelham, AL 35124
1.800.637.6047
www.rainbowtech.net



**USDA
CERTIFIED
BIOBASED
PRODUCT**
PRODUCT 40%

